


Contact Us:

Email: rwilson@wilsonswoodworks.com


<https://wilsonswoodworks.com>



Stop Loss Bags™ Filling Station

Stand materials:

We suggest a minimum of 5-6" of overall width for stability. A 2x6 works perfect, but use what you have laying around!



Plastic parts are available for purchase from:
<https://www.wilsonswoodworks.com/index.php/store/>

For those with 3D Printing capabilities. Free parts files are posted at
<https://www.thingiverse.com/thing:4663622>